

# MILLTEK

|             |          |
|-------------|----------|
| SYSTEM NO.  | SSXFD492 |
| DESCRIPTION | Cat-back |
| NOTES       |          |

## PARTS REQUIRED

| PART NO.        | DESCRIPTION                           | QUANTITY | IN PACKAGE |
|-----------------|---------------------------------------|----------|------------|
| <b>MSFD305</b>  | <b>Front Adapter to OE</b>            | <b>1</b> |            |
| 10MMWASHER      | 10mm Flat Washer Bzp                  | 2        |            |
| F1443           | 8mm S/Steel Flange                    | 1        |            |
| M10FLGNUT       | M10 Bzp Flange Nut serrated Only      | 2        |            |
| M10X35BZP       | M10 X 35mm Bzp Set Screw              | 2        |            |
| <b>MSFD306</b>  | <b>Front Resonator (Road+)</b>        | <b>1</b> |            |
| CHC79SS         | 79mm Band Clamp - 304 S/S             | 1        |            |
| <b>MSFD308</b>  | <b>Center Connecting Pipe</b>         | <b>1</b> |            |
| CHC79SS         | 79mm Band Clamp - 304 S/S             | 1        |            |
| <b>MSFD311</b>  | <b>Y Pipe</b>                         | <b>1</b> |            |
| CHC79SS         | 79mm Band Clamp - 304 S/S             | 1        |            |
| <b>MSFD313</b>  | <b>RH Connecting Pipe</b>             | <b>1</b> |            |
| CHC66.5SS       | 66.5mm Band Clamp-304 S/Steel         | 1        |            |
| <b>MSFD316</b>  | <b>LH Outlet Pipe (Tremor Models)</b> | <b>1</b> |            |
| CHC66.5SS       | 66.5mm Band Clamp-304 S/Steel         | 1        |            |
| <b>MSFD317</b>  | <b>RH Outlet Pipe (Tremor Models)</b> | <b>1</b> |            |
| CHC66.5SS       | 66.5mm Band Clamp-304 S/Steel         | 1        |            |
| <b>MSTIP250</b> | <b>4.5" Polished Tips</b>             | <b>2</b> |            |
| CHC66.5SS       | 66.5mm Band Clamp-304 S/Steel         | 2        |            |

## TECHNICAL INFORMATION

|       |  |
|-------|--|
| NOTES |  |
|-------|--|