

MILLTEK

SYSTEM NO.	SSXBM1295
DESCRIPTION	GPF/OPF Bypass
NOTES	OPF/GPF Bypass Requires Stage 2 ECU Software

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
F5161	Adapters to OE System	2	
CHC73SS	73mm Band Clamp 304 S/Steel	2	
CHC79SS	79mm Band Clamp - 304 S/S	2	
F7107	Chassis Brace	1	
MSBM358	LH OPF/GPF Bypass	1	
MSBM359	RH OPF/GPF Bypass	1	
MSBM425	LH Centre Silencer Bypass	1	
CHC79SS	79mm Band Clamp - 304 S/S	1	
MSBM426	RH Centre Silencer Bypass	1	
CHC79SS	79mm Band Clamp - 304 S/S	1	

TECHNICAL INFORMATION

NOTES	OE Exhaust Requires Cutting. Cut at the middle indent of the 3 marks on the OE pipework and deburr afterward. Some later cars only have one OE cut mark.
-------	--

