

MILLTEK

SYSTEM NO.	SSXBM1338
DESCRIPTION	GPF/OPF Bypass
NOTES	OPF/GPF Bypass Requires Stage 2 ECU Software

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
F5160	Adapter to Milltek Sport System	2	
CHC79SS	79mm Band Clamp - 304 S/S	2	
F7096	Chassis Brace Plate	1	
MSBM439	X Pipe	1	
CHC79SS	79mm Band Clamp - 304 S/S	2	
MSBM440	102MM / 4" Single Mid Pipe	1	

TECHNICAL INFORMATION

NOTES	OPF/GPF Bypass Requires Stage 2 ECU Software
-------	--