

MILLTEK

SYSTEM NO.	SSXP0185
DESCRIPTION	Cat-back
NOTES	Requires Stage 2 ECU remap

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSPO258	LH GPF/OPF Bypass	1	
8MMWASHER	8mm Flat Washer Bzp	5	
F3148	Aluminium Blanking Plug	2	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	5	
M8X35BZP	M8 X 35mm Bzp Hex Setzinc	5	
MSPO259	RH GPF/OPF Bypass	1	
8MMWASHER	8mm Flat Washer Bzp	5	
F3148	Aluminium Blanking Plug	2	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	5	
M8X35BZP	M8 X 35mm Bzp Hex Setzinc	5	
MSPO310	Rear Silencer Assembly	1	
8MMWASHER	8mm Flat Washer Bzp	12	
F3034	Gasket 1.5mm	4	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	12	
M8X35BZP	M8 X 35mm Bzp Hex Setzinc	12	
MSPO263	Outlet Pipes	2	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	2	
MSPO311	LH Valve Assembly	1	
MSPO312	RH Valve Assembly	1	
MSPO286	LH Mounting Bracket - PDK Cars Only	1	
MSPO287	RH Mounting Bracket - PDK Cars Only	1	
MSTIP251	4.5" Cerakote Black Tips	2	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	2	

TECHNICAL INFORMATION

NOTES	Requires Stage 2 ECU remap
-------	----------------------------