

# MILLTEK

|             |          |
|-------------|----------|
| SYSTEM NO.  | SSXH0300 |
| DESCRIPTION | Cat-back |
| NOTES       |          |

## PARTS REQUIRED

| PART NO.          | DESCRIPTION                            | QUANTITY | IN PACKAGE |
|-------------------|----------------------------------------|----------|------------|
| <b>F7098</b>      | <b>Heatshield for Rear Silencer</b>    | <b>1</b> |            |
| <b>MSHO133REP</b> | <b>Front Silencer Replacement Pipe</b> | <b>1</b> |            |
| CHC79SS           | 79mm Band Clamp - 304 S/S              | 1        |            |
| <b>MSHO134</b>    | <b>Centre Silencer</b>                 | <b>1</b> |            |
| CHC79SS           | 79mm Band Clamp - 304 S/S              | 1        |            |
| <b>MSHO135</b>    | <b>Rear Connecting Pipe</b>            | <b>1</b> |            |
| CHC79SS           | 79mm Band Clamp - 304 S/S              | 1        |            |
| <b>MSHO155</b>    | <b>Front Connecting Pipe with Flex</b> | <b>1</b> |            |
| F3116             | Gasket 1.5mm                           | 1        |            |
| <b>MSHO156</b>    | <b>Twin Rear Silencer</b>              | <b>1</b> |            |
| CHC79SS           | 79mm Band Clamp - 304 S/S              | 1        |            |
| <b>MSHO157REP</b> | <b>Valve Bypass Pipe</b>               | <b>1</b> |            |
| CHC79SS           | 79mm Band Clamp - 304 S/S              | 1        |            |
| <b>MSTIP250</b>   | <b>4.5" Tailpipe - Polished x 3</b>    | <b>3</b> |            |
| CHC66.5SS         | 66.5mm Band Clamp-304 S/Steel          | 3        |            |
| <b>MSVALVEDEL</b> | <b>Valve Delete Module</b>             | <b>1</b> |            |

## TECHNICAL INFORMATION

|       |  |
|-------|--|
| NOTES |  |
|-------|--|