

MILLTEK

SYSTEM NO.	SSXINE115
DESCRIPTION	Particulate Filter-back
NOTES	Requires OE System to be Cut

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU529	Polished Tip Assembly	2	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	2	
MSINE002	Axle Pipe	1	
CHC79SS	79mm Band Clamp - 304 S/S	1	
MSINE003	Rear Silencer Bypass	1	
CHC79SS	79mm Band Clamp - 304 S/S	1	
MSINE006	LH Outlet Pipe	1	
CHC66.5SS	66.5mm Band Clamp - 304 S/S	1	
MSINE007	RH Outlet Pipe	1	
CHC66.5SS	66.5mm Band Clamp - 304 S/S	1	

TECHNICAL INFORMATION

NOTES	Requires OE System to be Cut
-------	------------------------------